

**Flood Control Project Maintenance  
Levee Inspections**

**Fall 2018 Levee Maintenance Deficiency Summary Report**

Overall LMA & Unit Ratings, including USACE Erosion Survey

**Sacramento River Basin**

**\*\* SBFCA currently has operation and maintenance obligations during project construction and closeout.**

<b>LD0009</b>	Overall LMA Rating	Total LMA Miles						
<b>Levee District No. 0009 (Sutter County)</b>	<b>A</b>	<b>6.25</b>						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
<i>Earthen Levee</i>								
Encroachments					0.34			
Animal Control	0.01		0.01	0.16%				
<i>LMA Totals:</i>	0.01	0.00	0.01	0.16%	0.34	0.00	0.00	0.00

  

<b>Unit No. 01 Sutter County, Feather River RB</b>	Overall Unit Rating	Total Unit Miles						
<b>LD0009</b>	<b>A</b>	<b>6.25</b>						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
<i>Earthen Levee</i>								
Encroachments					0.34			
Animal Control	0.01		0.01	0.16%				
<i>Unit Totals:</i>	0.01	0.00	0.01	0.16%	0.34	0.00	0.00	0.00

**Flood Control Project Maintenance  
Levee Inspections****LMA District Cover Sheet****Fall 2018 Levee Inspection Results****Levee District No. 0009 (Sutter County)**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
† Overall LMA Rating (Fall Only)			A	

\*\* Non-receipt of Summer or Winter Inspection  
Reports may effect overall annual rating.

† **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

**FALL INSPECTIONS:** The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2018 Levee Inspection Results**

**Levee District No. 0009 (Sutter County)**

Waterway			Bank	Unit Miles
Unit No. 01 Sutter County, Feather River			Right	6.25
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			<b>A</b>	
Date of Inspection	3/13/2018 - 3/13/2018		10/18/2018 - 10/18/2018	
DWR Inspector	Sterling York		Sterling York	
Accompanied By	David Schmidl		David Schmidl	

**Summer & Winter Inspections**

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

*The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.*

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2018**

**Levee District No. 0009 (Sutter County)**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter County, Feather River	Right	6.25	10/18/2018 10/18/2018	Sterling York

LM Start		Rating **	A	Issue No.	4
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_LD0009_01_s_2013_4				
Comment Code					
Inspector Comment					
LD 9 has flood fight supplies on hand and coordinates with other local levee districts in the flood fight supply staging program.					

No Photos

LM Start		Rating **	A	Issue No.	5
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_LD0009_01_s_2013_5				
Comment Code					
Inspector Comment					
The levee district has stated in the past that they have a copy of the O&M manuals.					

No Photos

LM Start		Rating **	A	Issue No.	6
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_LD0009_01_s_2013_6				
Comment Code					
Inspector Comment					
The district has attended the Flood Fight class put on by RD 784 and DWR.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

## Levee District No. 0009 (Sutter County)

Page 2 of 3

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2018**

**Levee District No. 0009 (Sutter County)**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter County, Feather River	Right	6.25	10/18/2018 10/18/2018	Sterling York

LM Start	5.66	Rating **	M	Issue No.	20
LM End	6.00	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.247349 °	39.252258 °
				-121.637341 °	-121.637077 °
DWR ID	DWR_LD0009_01_f_2016_20				
Comment Code					
DT : Ditch					
Inspector Comment					
Ditch at the toe of the landside levee.					

Photo 1 of 1 : FA\_2018\_LD0009\_202\_20\_20180918\_00004.jpg



View looking upstream of ditch at the toe of the landside levee.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---